

Hydrogeological Report on NW Aboriginal Lands well monitoring – October 1998 to April 1999

REPORT BOOK 2000/00005

by

Sandy Dodds and Lloyd Sampson

Department for Water Resources, Groundwater

FEBRUARY 2000



**PRIMARY INDUSTRIES
AND RESOURCES SA**

© Department of Primary Industries and Resources South Australia

This report is subject to copyright. Apart from fair dealing for the purposes of study, research, criticism or review as permitted under the Copyright Act, no part may be reproduced without written permission of the Chief Executive of Primary Industries and Resources South Australia

PRIMARY INDUSTRIES AND RESOURCES SOUTH AUSTRALIA

REPORT BOOK 2000/00005

| CONTENTS | PAGE |
|--|------|
| ABSTRACT | 4 |
| INTRODUCTION | 4 |
| ANALYSIS OF LOGGING DATA | 4 |
| Indulkana | 4 |
| Mimili | 5 |
| Fregon | 5 |
| Kenmore Park | 5 |
| Pukatja (Ernabella) | 5 |
| Amata | 5 |
| Kalka | 6 |
| Pipalyatjara | 6 |
| SUMMARY | 6 |
| FIGURES | 7 |
| Figure 1 Locality Plan (<i>Plan No. 200213-001</i>) | 8 |
| Figure 2 Well locations - Indulkana (<i>Plan No. 200213-088</i>) | 9 |
| Figure 3 Indulkana Rainfall - October 1998 to April 1999 | 10 |
| Figure 4 Indulkana IMB-19; Hourly SWL and Pump Rate | 11 |
| Figure 5 Indulkana IMB-19A; Hourly SWL and Pump Rate | 12 |
| Figure 6 Indulkana IMB-25; Hourly SWL and Pump Rate | 13 |
| Figure 7 Indulkana IMB-26; Hourly SWL and Pump Rate | 14 |
| Figure 8 Indulkana IMB-27; Hourly SWL and Pump Rate | 15 |
| Figure 9 Well locations - Mimili (<i>Plan No. 200213-003</i>) | 16 |
| Figure 10 Mimili Rainfall - October 1998 to April 1999 | 17 |
| Figure 11 Mimili M-1; Hourly SWL and Pump Rate | 18 |
| Figure 12 Mimili M-3; Hourly SWL and Pump Rate | 19 |
| Figure 13 Well locations - Fregon (<i>Plan No. 200213-004</i>) | 20 |
| Figure 14 Fregon Rainfall - October 1998 to April 1999 | 21 |
| Figure 15 Fregon FRG-1; Hourly SWL and Pump Rate | 22 |
| Figure 16 Fregon FRG-7; Hourly SWL and Pump Rate | 23 |
| Figure 17 Fregon FRG-14; Hourly SWL and Pump Rate | 24 |
| Figure 18 Fregon FRG-E4; Hourly SWL and Pump Rate | 25 |
| Figure 19 Well locations - Kenmore Park (<i>Plan No. 200213-005</i>) | 26 |
| Figure 20 Kenmore Park Rainfall; October 1998 to April 1999 | 27 |
| Figure 21 Kenmore Park KP-6; Hourly SWL and Pump Rate | 28 |
| Figure 22 Kenmore Park KP-7; Hourly SWL and Pump Rate | 29 |
| Figure 23 Well locations - Pukatja (<i>Plan No. 200213-006</i>) | 30 |
| Figure 24 Pukatja Rainfall - October 1998 to April 1999 | 31 |
| Figure 25 Pukatja E-1; Hourly SWL and Pump Rate | 32 |
| Figure 26 Pukatja E-12; Hourly SWL and Pump Rate | 33 |
| Figure 27 Pukatja E-42; Hourly SWL and Pump Rate | 34 |
| Figure 28 Pukatja E-44; Hourly SWL and Pump Rate | 35 |
| Figure 29 Pukatja E-45; Hourly SWL and Pump Rate | 36 |
| Figure 30 Pukatja E-97B; Hourly SWL and Pump Rate | 37 |
| Figure 31 Pukatja E-97L; Hourly SWL and Pump Rate | 38 |

| | | |
|---|--|----|
| Figure 32 | Well locations - Amata (<i>Plan No. 200213–007</i>) | 39 |
| Figure 33 | Amata Rainfall - October 1998 to April 1999 | 40 |
| Figure 34 | Amata A–15; Hourly SWL and Pump Rate | 41 |
| Figure 35 | Amata A–17; Hourly SWL and Pump Rate | 42 |
| Figure 36 | Amata A–26; Hourly SWL and Pump Rate | 43 |
| Figure 37 | Well locations - Pipalyatjara and Kalka (<i>Plan No. 200213–008</i>) | 44 |
| Figure 38 | Kalka Rainfall - October 1998 to April 1999 | 45 |
| Figure 39 | Kalka KA–1; Hourly SWL and Pump Rate | 46 |
| Figure 40 | Kalka KA–2; Hourly SWL and Pump Rate | 47 |
| Figure 41 | Kalka KA–3; Hourly SWL and Pump Rate | 48 |
| Figure 42 | Pipalyatjara Rainfall - October 1998 to April 1999 | 49 |
| Figure 43 | Pipalyatjara PIP–95; Hourly SWL and Pump Rate | 50 |
| Figure 44 | Pipalyatjara PIP–96; Hourly SWL and Pump Rate | 51 |
| APPENDIX A – OPERATIONAL REPORT, B.J. TRAEGER | | 52 |
| APPENDIX B – TABLES OF WELLS AND EQUIPMENT | | 58 |

**PRIMARY INDUSTRIES AND RESOURCES
SOUTH AUSTRALIA**

REPORT BOOK 2000/00005

DME 99/0665

HYDROGEOLOGICAL REPORT ON NW ABORIGINAL LANDS WELL MONITORING – OCTOBER 1998 TO APRIL 1999

Sandy Dodds and Lloyd Sampson

Monitoring equipment is now in place in 29 wells, which supply all groundwater to 8 major communities in the Anangu Pitjantjatjara lands. The equipment provides standing water level (SWL) and pumping rates on an hourly basis for each well; information which should give a good indication of the sustainability of the water supply. Additionally, one rain gauge at each community gives similar information on precipitation and provides guidance on recharge.

INTRODUCTION

This report comprises brief comments on the current download of data. A more comprehensive report covering all monitoring data to date and the results of geophysical logging of the wells is in the process of compilation and should be ready within two months.

ANALYSIS OF LOGGING DATA

INDULKANA

Well 19. While there is no indication of depletion in this period, the well is showing a high response to the pumping rate of ~0.6 L/s. This has long term implications. The slow recovery of the well in the second half of December is caused by pumping at such a low rate as to be invisible on the graph (0.001–0.002 L/s).

Well 19A. The failure of the logger in November 1998 resulted in too small a data set to show long term trends. However, the well is evidently being pumped dry within two hours at the currently used rate of 0.8 L/s and never fully recovers in the intervening 12 hours. The long term effects of this may be evident in the next download of data over a full 6 months.

Well 25. This well, the major water supplier in the area, is showing evidence of slow depletion, but has stood up well to steady pumping. Prior to recovery in April 1999 in response to a week without pumping, the water levels had declined by over a metre for the period. The well appears capable of sustaining current pumping rates.

Well 26. No depletion; the well seems satisfactory so long as pumping rates are kept low. The well shows a high response to pumping rates of ~0.6 L/s, but minimal response to rates of 0.1 L/s.

Well 27. The well is bottoming out in spite of low and intermittent pumping rates. The water level fell by over 5 m over the monitoring period.

Rainfall. The rainfall gauge on 19 shows significant falls intermittently through this period, but no sustained periods of rain such as would be ideal for recharge. There is no obvious recharge indication in any well.

MIMILI

Well M1. No sign of depletion at these pumping rates.

Well M3. No sign of depletion at these pumping rates.

Rainfall. As for Indulkana.

FREGON

Well 1. The well is gradually depleting, even at these low pumping rates and sparse intervals. The water level declined by 0.3 m over the monitoring period.

Well 7. Only the first half of this record is valid, as the equipment failed in mid January. From the data available there is no sign of depletion.

Well 14. It does appear that this well is depleting, but the time span of the data and irregular pumping intervals make the conclusion unsure. Analysis of more data will clarify the picture. The water level fell by 0.4 m over the monitoring period.

Well E4. Slow depletion appears to be taking place, as for well 14 above. The water level fell by 0.2 m over the monitoring period.

Rainfall. There were intermittent falls in this period, but less than occurred at Indulkana or Mimili.

KENMORE PARK

Well 6. No sign of depletion, but SWL figures are evidently wrong at times (November-December), and look illogical at other times (January-February). While this data is not to be trusted, the later data between mid-February and April appears better and indicates that the well is capable of sustaining current pumping rates.

Well 7. Pumping has been of short duration and the well appears to have a fragile supply. The water level has declined by 0.2 m over the monitoring period.

Rainfall. Intermittent low falls in this period.

PUKATJA (ERNABELLA)

Well 1. In spite of the lack of pumping this well shows a steady drop of 0.3 m over the period, as a result of either pumping in adjacent wells or movement of water downstream. There is no evidence of recharge.

Well 12. The well was pumped well nigh continuously over the period with no sign of aquifer depletion.

Well 42. This well was not pumped much in this period. In the absence of pumping the SWL shows a general drop of 0.2 m, but also some indications of rises that might indicate recharge, even though the correspondence with rainfall events is poor. The data warrants further study, especially when more data is available.

Well 44. Shows a steady drop of 0.4 m in the absence of pumping, as for well 1. No evidence of recharge.

Well 45. While depletion seems to be taking place, the erratic pumping rates make accurate determination difficult. The SWL seems to have dropped about 2 m

Well 97B. Insufficient data.

Well 97L. Insufficient data.

Rainfall. There was scattered, appreciable rainfall during the period.

AMATA

Well 15. There are possible indications of depletion, but these are somewhat obscured by variations in pumping rate and duration. A greater data time window will clarify it.

Well 17. As for 15. The best estimate is a decline in water level of 0.3–0.5 m.

Well 26. The indications of gradual depletion are fairly clear but the rate is, again, slow.

Rainfall. Heavier intermittent falls of rain.

KALKA

Well 1. No sign of depletion.

Well 2. No sign of depletion.

Well 3. No sign of depletion.

Rainfall. Similar to Amata.

PIPALYATJARA

Well 95. No sign of depletion.

Well 96. No sign of depletion.


Rainfall. Similar to Kalka.

SUMMARY

On a community basis, wells at Mimili, Kalka and Pipalyatjara show no sign of stress or depletion. Those at Fregon, Kenmore Park and Amata show possible signs of depletion, but not such as to be sure over this time period. Indulkana did not show significant depletion (except IMB-27), but all wells have a high drawdown for relatively low pumping rates over short intervals, which has long term sustainability implications. At Ernabella three wells, which were either not pumped or were used very little, all showed a small but significant lowering of SWL, indicating that supplies are limited in this area. Well E-12 went against this trend, showing no depletion in spite of long term pumping at over 1 L/s. There is insufficient information on the two new wells.

It is worth noting the wide range in rainfall figures over this period, from 97.2 mm at Fregon to 342 mm at Pipalyatjara. Overall rainfall was higher in the west than in the east. It will be interesting to note whether this distribution persists in other time periods.

Figures






Figure 3 Indulkana Rainfall - October 1998 to April 1999




Figure 4 Indulkana IMB-19; Hourly SWL and Pump Rate

INDULKANA 19a




Figure 5 Indulkana IMB-19A; Hourly SWL and Pump Rate

INDULKANA 25




Figure 6 Indulkana IMB-25; Hourly SWL and Pump Rate

INDULKANA 26




Figure 7 Indulkana IMB-26; Hourly SWL and Pump Rate

INDULKANA 27




Figure 8 Indulkana IMB-27; Hourly SWL and Pump Rate




Figure 9
AV3:300213-003

MIMILI M-3




Figure 10 Mimili Rainfall - October 1998 to April 1999

MIMILI M-1




Figure 11 Mimili M-1; Hourly SWL and Pump Rate

MIMILI M-3





Figure 12 Mimili M-3; Hourly SWL and Pump Rate






Figure 14 Fregon Rainfall - October 1998 to April 1999

FREGON FRG-01




Figure 15 Fregon FRG-1; Hourly SWL and Pump Rate

FRG-7




Figure 16 Fregon FRG-7; Hourly SWL and Pump Rate




Figure 17 Fregon FRG-14; Hourly SWL and Pump Rate

FREGON FRG-E4





Figure 18 Fregon FRG-E4; Hourly SWL and Pump Rate



KENMORE PARK KP-7




Figure 20 Kenmore Park Rainfall - October 1998 to April 1999

KENMORE PARK KP-6




Figure 21 Kenmore Park KP-6; Hourly SWL and Pump Rate

KENMORE PARK KP-7




Figure 22 Kenmore Park KP-7; Hourly SWL and Pump Rate




Figure 23
AV3:200213-006

PUKATJA E-42




Figure 24 Pukatja Rainfall - October 1998 to April 1999

PUKATJA E-01




Figure 25 Pukatja E-1; Hourly SWL and Pump Rate

PUKATJA E-12




Figure 26 Pukatja E-12; Hourly SWL and Pump Rate

PUKATJA E-42




Figure 27 Pukatja E-42; Hourly SWL and Pump Rate

PUKATJA E-44




Figure 28 Pukatja E-44; Hourly SWL and Pump Rate

PUKATJA E-45




Figure 29 Pukatja E-45; Hourly SWL and Pump Rate

PUKATJA E-97b




Figure 30 Pukatja E-97B; Hourly SWL and Pump Rate

PUKATJA E-97I






Figure 31 Pukatja E-97L; Hourly SWL and Pump Rate



AMATA 15



October 1998 to April 1999

Figure 33 Amata Rainfall - October 1998 to April 1999

AMATA 15





Figure 34 Amata A-15; Hourly SWL and Pump Rate

AMATA 17



October 1998 to April 1999

Figure 35 Amata A-17; Hourly SWL and Pump Rate

AMATA 26




Figure 36 Amata A-26; Hourly SWL and Pump Rate




Figure 37
AV3:200213-008

KALKA KA-3




Figure 38 Kalka Rainfall - October 1998 to April 1999

KALKA KA-1




Figure 39 Kalka KA-1; Hourly SWL and Pump Rate

KALKA KA-2




Figure 40 Kalka KA-2; Hourly SWL and Pump Rate

KALKA KA-3




Figure 41 Kalka KA-3; Hourly SWL and Pump Rate

PIPALYATJARA PIP-95




Figure 42 Pipalyatjara Rainfall - October 1998 to April 1999

PIPALYATJARA PIP-95




Figure 43 Pipalyatjara PIP-95; Hourly SWL and Pump Rate

PIPALYATJARA PIP-96




Figure 44 Pipalyatjara PIP-96; Hourly SWL and Pump Rate

Appendix A

Operational Report

B.J. Traeger

To:- J. Alvey, M. Goodchild, S. Dodds.
 From:- B. Traeger
 Date:- 10 May, 1999
 SUBJECT:- N.W. Aboriginal Lands Data loggers.

The following report relates to results down loaded in April 1999.

INDULKANA (15 and 16 April 1999)

| BORE | SWL(Actual) | SWL(logger) | Flowrate | Accumulated Flow m ³ |
|------|-------------|-------------|----------|---------------------------------|
| 25 | 13.01 | 13.010 | N/A | 6039.0 |
| 19A | 26.640 | 26.640 | N/A | 1828.67 |
| 19 | 16.660 | 16.660 | 0.64 | 954.133 |
| 26 | Flowing | | N/A | 1145.59 |
| 27 | 31.075 | 31.030 | 0.0163 | 1528.68 |
| IR1 | 37.890 | | | |
| IR2 | 55.500 | | | |

Notes:-

- 19A Data logger was unable to communicate. Data logger S/N 311183 was removed and replaced with logger S/N 311208.
 The flow meter was also faulty with no 4–20mA output. The faulty unit S/N A97–79248 was removed and replaced with spare S/N 912498 D.
 The data logger had stopped logging after 2200 hours on the 6 November 1998, this corresponds to the commencement of rainfall at bore 19 and may well have been caused by a lightning strike.
- 26 SWL datum may have been set to 39.097 m, the set up of this bore will need to be closely checked at the next site visit. The pump in this bore has deteriorated substantially since February 1999 which can be seen by the drop off in flow rate. I understand the pump has recently been replaced.
- 27 SWL datum was reset by 0.045 m.
 It appears that this bore has been over pumped and should be isolated and given time to recover.
- IR1 The new bore Indulkana Range 1 SWL was measured but there is no monitoring equipment installed. The bore has a temporary power supply and pipe line to the community system.
- IR2 SWL was not measured but from the geophysical logging the SWL is 55.5 m.
 Accumulated flow for all Indulkana bores was from 13 October 1998 to 15 April 1999
 Rain gauge reading at bore 19 was 147.4 mm.

MIMILI (18 April 1999)

| BORE | SWL(Actual) | SWL(logger) | Flowrate | Accumulated Flow m ³ |
|------|-------------|-------------|----------|---------------------------------|
| M1 | 16.180 | 16.180 | 1.6 | 11502 |
| M3 | 10.950 | 10.950 | 1.2 | 8126 |

Notes:-

Accumulated flow for all Mimili bores was from 13 October 1998 to 18 April
 Rain gauge reading at bore M3 was 165.6 mm.

FREGON (18 April 1999)

| BORE | SWL(Actual) | SWL(logger) | Flowrate | Accumulated Flow m ³ |
|--------|-------------|-------------|----------|---------------------------------|
| FRG 1 | 10.115 | 10.115 | 1.82 | 8583 |
| FRG 14 | 11.030 | 11.030 | 2.54 | 18325 |
| FRG 7 | 10.340 | 10.340 | N/A | 14178 |
| FRG E4 | 10.050 | 10.050 | 1.8 | 7258.94 |

Notes:-

- FRG 1 Flow rate may have been read in error, the normal logged pump rate is 0.25 L/s, this will need a closer look at the next visit.
- FRG 14 Data logger was unable to communicate. Fault was found to be a blown fuse in the logger, after replacement the logger was successfully down loaded. The logger had been operational until the 25 March 1999, however after that date no data was recorded. There is no obvious reason which caused the logger to fail.
- FRG 7 The 2100P pressure transducer (S/N 210359) was found to faulty and was replaced with a spare unit S/N 210 435. From the data recorded it would appear that the pressure transducer began to fail during mid January 1999.

Accumulated flow for all Fregon bores was from 14 October 1998 to 18 April 1999.

Rain gauge reading at bore FRG 14 was 97.2 mm from 14 October 1998 to 25 March 1999 when the logger failed.

KENMORE PARK (14 October 1998)

| BORE | SWL(Actual) | SWL(logger) | Flowrate | Accumulated Flow m ³ |
|-------|-------------|-------------|----------|---------------------------------|
| KP 6 | 10.095 | 10.345 | 1.74 | 10529 |
| KP 7 | 11.290 | 11.290 | 1.45 | 978.134 |
| KP 98 | 10.660 | | | |

Notes:-

- KP 6 SWL reset by 0.250 m. The reading recorded for SWL for the period 2 November 1998 to 8 December 1998 are false. It appears that either the air line was disconnected or the valves in the 2100P transducer did not seal. The situation appears to have corrected its self but this will be reported to the manufacturer and the equipment checked at the next down load trip.
- KP98 473.89 hours at 13 April 1999
320.5 hours at 14 October 1998
153.39 hours total use.

Accumulated flow for all Kenmore Park bores was for the period 14 October 1998 to 13 April 1999.

Rain gauge reading at bore KP 7 was 99 mm.

ERNABELLA (13/14 April 1999)

| BORE | SWL(Actual) | SWL(logger) | Flowrate | Accumulated Flow m ³ |
|------|-------------|-------------|----------|---------------------------------|
| E01 | 8.635 | 8.717 | 0 | NIL |
| E12 | 8.515 | 8.830 | 1.225 | 18280 |
| E42 | 9.890 | 9.833 | 0.469 | 638.44 |
| E44 | 12.170 | 15.150 | 0 | NIL |
| E45 | 12.550 | 12.488 | 0.829 | 9802 |
| E97B | 15.325 | | 2.1 | |
| E97L | 17.850 | | 1.085 | |

Notes:-

- E01 SWL datum reset by 0.082 m. The bore has not been used for the monitoring period.
- E12 SWL datum reset by 0.315. Pump was running but no flow. It was found that the pump had broken away from the black poly pipe pump column. The data shows that the pump connection broke away after 1500 hrs. on 11 April 1999.
- E42 SWL datum reset by 0.057
- E44 SWL datum reset by 2.980. No flow data because the pump has not been replaced. This site will require a close check at the next visit as the SWL datum may have been in-correctly reset with the air tube out of water.
- E45 SWL datum reset by 0.062
- E97B New installation of equipment on 10 April 1999
- E97L New installation of equipment on 10 April 1999.

Both new sites were checked on 14 April 1999 and found to be operating correctly.
Accumulated flow for all other Ernabella bores was from 14 October 1998 to 14 April 1999
Rain gauge reading at bore E42 was 133.8 mm

AMATA (12 April 1999)

| BORE | SWL(Actual) | SWL(logger) | Flowrate | Accumulated Flow m ³ |
|------|-------------|-------------|----------|---------------------------------|
| A15 | 14.250 | 14.502 | 1.924 | 16300 |
| A17 | 14.405 | 14.350 | 0.900 | 9685.14 |
| A26 | 16.905 | 16.895 | 1.020 | 1361.2 |

Notes:-

- A15 SWL datum was reset by 0.252 m.
- A17 SWL datum was reset by 0.055 m.
- A26 SWL datum was reset by 0.010 m.

Accumulated flow for Amata bores was from 15 October 1998 to 12 April 1999.
Rain gauge reading at bore A15 was 238.4 mm.

KALKA (16 October 1998)

| BORE | SWL(Actual) | SWL(logger) | Flowrate | Accumulated Flow m ³ |
|------|-------------|-------------|----------|---------------------------------|
| KA 1 | 27.125 | 27.197 | 0.102 | 928.94 |
| KA 2 | 27.955 | 27.895 | 0.122 | 1733.75 |
| KA 3 | 19.250 | 19.281 | 1.103 | 6310.3 |

Notes:-

KA 1 SWL datum was reset by 0.072 m.

KA 2 SWL datum was reset by 0.060 m. The flow rate was reduced to approx. 0.125 L/s.

KA 3 SWL datum was reset by 0.020 m.

Accumulated flow for all Kalka bores was from 16 October 1998 to 11 April 1999

Rain gauge reading at bore KA 2 was 268.4 mm for the same period.

PIPALYATJARA (16 October 1998)

| BORE | SWL(Actual) | SWL(logger) | Flowrate | Accumulated Flow m ³ |
|--------|-------------|-------------|----------|---------------------------------|
| PMB 95 | 16.910 | 16.959 | 1.45 | 9902.99 |
| PMB 96 | 20.820 | 20.830 | 1.45 | 6564.090 |
| MD 13 | 14.510 | N/A | N/A | |

Notes:-

PMB95 SWL datum was reset by 0.040 m.

PMB96 SWL datum was reset by 0.010 m.

MD13 SWL was measured and a note of hours run meter read,
9193.37 hours at 10 April 1999
9193.37 hours at 16 October 1998
0.00 hours total use.

Accumulated flow for all Pipalyatjara bores was from 16 October 1998 to 10 April 1999.

Rain gauge reading at bore PMB 95 was 342 mm from 16 October 1998 to 10 April 1999.

CONCLUSIONS AND OBSERVATIONS

This down load trip was made in conjunction with the geophysical logging and video survey of all the communities water supply bores and the establishment of monitoring equipment at two new bores in the Turkey Bore area. To achieve the work load in a reasonable period of time I gave instruction to Richard Martin (Technical Officer) regarding the down loading of the loggers, this allowed me to undertake the geophysical logging and video surveys. M. Goodchild and S. Wurst removed and replaced the 31 pump systems.

Generally the monitoring equipment is operating extremely well, there were a few situations worth mentioning.

- Equipment failures resulted in some lost data at:
 - Indulkana 19A data logger required a replacement fuse, but the flow meter was removed and returned for repair, the failures were probably caused by a lightning strike.
 - Fregon 7 were a pressure transducer failed and was found to have a significant amount of condensate in the 2100P. The unit has been returned for repair.
 - Fregon 14 were a logger stopped logging for no apparent reason, the fault was a blown fuse which was replaced.
 - Kenmore Park 6 were a pressure transducer appears to have failed for a period of time but corrected itself, possibly due to a sticking valve. No action taken at this stage.
- A number of sites had variations of SWL between the logged values and the actual measured values. Most variations were minor with the exception of three sites, Amata A15, Ernabella E44, and Kenmore Park KP6. The 2100P pressure transducers at these sites will require close scrutiny during the next field visit.
- It appears that two sites may have had SWL datum set incorrectly due to operating errors and will also have to be checked during the next trip. Ernabella E44, and Indulkana I26 bores.

It should be noted at this point that because the pumps have all been disturbed, removed and replaced, the SWL measurements during the next trip may have numerous variations between logged and measured values due to the settling of the pump columns.

During the trip the two new sites at Turkey Bore area for supply to Ernabella have been equipped and are now being monitored. The equipment used at these sites was in stock, and now leaves the minimum amount of equipment considered necessary for operating spares. To equip the two new bores at Indulkana Range new equipment will have to be purchased.

Appendix B

Tables of wells and equipment

| Area | Well identification | Well unit number | Flowmeter | SWL transducer and logger | Logger format | Comments |
|--------------|---------------------|------------------|-----------|---------------------------|---------------|---------------------------|
| Indulkana | IMB-19 | 5544-101 | Dec 1997 | Dec 1997 | 1 | Also rainguage |
| | IMB-19A | 5544-132 | Dec 1997 | Dec 1997 | 2 | |
| | IMB-25 | 5544-157 | Pre 1997 | Pre 1997 | 2 | |
| | IMB-26 | 5544-158 | Dec 1997 | Dec 1997 | 2 | |
| | IMB-27 | 5544-159 | Dec 1997 | Dec 1997 | 2 | |
| | IR-1 | 5544-172 | | | | To be equiped late 1999 |
| | IR-2 | 5544-169 | | | | To be equiped late 1999 |
| | IR-3 | 5544-170 | | | | To be equiped late 1999 |
| | | | | | | |
| Pukatja | E-01 | 5345-06 | Dec 1997 | Dec 1997 | 2 | |
| | E-12 | 5345-12 | Dec 1997 | NONE | 2 | |
| | E-42 | 5345-33 | Dec 1997 | Dec 1997 | 1 | Rainguage |
| | E-44 | 5345-85 | Dec 1997 | Dec 1997 | 2 | |
| | E-45 | 5345-84 | Pre 1997 | Pre 1997 | 2 | Transducer replaced 12/97 |
| | E97B | 5345-114 | Apr 1998 | Apr 1998 | 2 | |
| | E97L | 5345-124 | Apr 1998 | Apr 1998 | 2 | |
| | | | | | | |
| Kenmore Park | KP-6 | 5345-67 | Pre 1997 | Pre 1997 | 2 | |
| | KP-7 | 5345-68 | Dec 1997 | Dec 1997 | 1 | Rainguage |
| | | | | | | |
| Mimili | M-1 | 5443-25 | Jan 1998 | Jan 1998 | 2 | |
| | M-3 | 5443-28 | Pre 1997 | Pre 1997 | 1 | Transducer replaced 12/97 |
| | | | | | | Rainguage |
| Fregon | FRG-01 | 5344-09 | Pre 1997 | Pre 1997 | 2 | Transducer replaced 12/97 |
| | FRG-07 | 5344-31 | Jan 1998 | Jan 1998 | 2 | |
| | FRG-14 | 5344-47 | Jan 1998 | Jan 1998 | 1 | Rainguage |
| | FRG-E4 | 5344-19 | Jan 1998 | Jan 1998 | 2 | |
| | | | | | | |
| Amata | A-15 | 5145-55 | Pre 1997 | Pre 1997 | 1 | Rainguage |
| | A-17 | 5145-84 | Jan 1998 | Jan 1998 | 2 | |
| | A-26 | 5145-19 | Jan 1998 | Jan 1998 | 2 | |
| | | | | | | |
| Pipalyatjara | PIP-95 | 4745-95 | Jan 1998 | Jan 1998 | 1 | Rainguage |
| | PIP-MD13 | 4745-92 | Jan 1998 | NONE | | Rarely used – run for 31 |
| | PIP-96 | 4745-96 | Pre 1997 | Pre 1997 | 2 | Hours Mar-Oct/98 |
| | | | | | | |
| Kalka | KA-1 | 4745-78 | Jan 1998 | Jan 1998 | 2 | |
| | KA-2 | 4745-94 | Jan 1998 | Jan 1998 | 2 | |
| | KA-3 | 4745-85 | Jan 1998 | Jan 1998 | 1 | Rainguage |
| | | | | | | |