

RB 55/64

DEPARTMENT OF MINES  
SOUTH AUSTRALIA  
GEOLOGICAL SURVEY  
NON FERROUS METALS SECTION  
GEOLOGICAL INVESTIGATION OF LEAKAGE  
FROM AROONA DAM  
FINAL REPORT ON DRILLING

by

W. Johnson  
Senior Geologist

NON FERROUS METALS SECTION  
GEOLOGICAL SURVEY

TABLE OF CONTENTS

Introduction  
Geology  
Engineering Geology  
Remedial Measures  
Conclusions & Recommendations

APPENDIX I

Graphic Logs of Diamond Drill Holes

PLANS ACCOMPANYING REPORT

<u>No.</u>		<u>Scale</u>
49-57	Leigh Creek Coal Field Aroona Dam Site - Geological Plan and Cross Section.	100' = 1"
62-613	Geological Investigation Aroona Dam Sections across and along ridge forming reservoir rim downstream of dam - left abutment	

Rept. Bk. 55/64  
G.S. 2438  
D.M. 961/58  
NFM. 135

3rd September, 1962

DEPARTMENT OF MINES  
SOUTH AUSTRALIA

GEOLOGICAL INVESTIGATION OF LEAKAGE

FROM AROONA DAM

FINAL REPORT ON DRILLING.

INTRODUCTION

Drilling of the four diamond drill holes recommended in the interim report\* was completed on 30/7/62 and pressure water testing of the holes was done in the same week.

This present report discusses the results of drilling and testing and the remedial measures indicated.

GEOLOGY

The main features of the geology which require reiterating are the dip of the thin bedded quartzites with their interbedded shaley sandstones upstream towards the dam (northerly) and their strike across the narrow ridge forming the reservoir rim, on the eastern side of the dam; the presence of numerous joints of two main systems; the narrowness of the ridge and the presence of a blanket of talus up to 15 feet vertical thickness on the western slope of the ridge.

ENGINEERING GEOLOGY:

The results of the drilling and testing broadly confirm the supposition that leakage is coming through the ridge in a network of interconnecting cracks rather than through a number of discrete cracked and fractured fault zones.

The cores of the diamond drill holes testify to the multitude of cracks along joints. Total number of joints in the cores were counted and the count ranged from 40 joints in

---

\* JOHNSON, W., 1962 - Interim Report on Leakage from the rim of Aroona Reservoir.  
UNPUBLISHED REPORT, DEPT. OF MINES, S. AUST.  
54/155

a 14 feet long section of the core of AL3 to 200 joints in a 19 feet long section of the core of AL2. The majority of these cracks are tight. This is shown by the pump-in water tests. In AL2 between 52 feet and 81 feet the loss was .58 g.p.m. under a collar pressure of 20 p.s.i. and 280 joints were counted in this section. In AL3 the loss between 52 feet and 81 feet was 8.7 g.p.m. under a collar pressure of 20 p.s.i. and 82 joints were counted.

The general tightness of individual cracks is confirmed by a calculation of the mass permeability of the ridge over the 1000 feet long section downstream of the abutment of the dam. Assuming an average water depth in the reservoir of 55 feet, a leakage rate of 8,000,000 gallons a week, and an average water gradient of .1 in the ridge, the permeability works out as 10 millidarcies, which is well down in the range of permeabilities of naturally occurring materials.

The water test results demonstrate also the effect of position in the ridge on the opening of the cracks. In D.D.H. AL3 no pressure was obtained with the packer set at 41.5 feet below the surface (maximum pump rate 13 g.p.m.) and generally losses were greater in this hole than in the other 3 holes. Cores from the holes and the profiles across the ridge show that AL3 is in the narrowest section of the ridge and at a position where the talus is thicker. This may be a sufficient cause of the increased opening of the cracks.

Owing to the steepness of the slope of the ridge the thickness of rock between the hole and the slope surface increases comparatively slowly with depth. The effect of this is shown in the water test results. In each hole the increase in rate of water loss is proportional to the length of hole tested, up to a certain depth below the surface, varying in each hole. At this depth the rate suddenly increases, indicating a sharp increase in permeability of the surrounding rock. As discussed in the previous paragraph the variation in depth at which this

occurs is due probably to the situation of the hole in relation to the bedrock surface.

Water levels in the various holes show clearly the increase in groundwater gradient southwards from the left abutment of the dam. This can be due only to a decrease in permeability southwards, which is consistent with the expected tightening of the cracks where the ridge becomes wider and higher.

### REMEDIAL MEASURES

The investigations have shown that it should be possible to prevent most of the leakage by sealing the network of cracks in the ridge through which the water is flowing. It remains to discuss how best this can be accomplished.

In my opinion the grouting of the cracks by a single row of holes, commencing at the left abutment of the dam and finishing between AL3 and AL4, would stop 90% of the leakage. Grouting any other length would stop an amount of the leakage proportional to the length grouted.

It would be unnecessary to grout below R.L. 805 as the indications are that the cracks below this level are tight. It would be unnecessary also to grout above R.L. 860. Therefore it is suggested that if grouting is done that the holes be drilled from a bench excavated in talus to intersect the talus/bedrock interface at R.L. 860.

Because of the general narrowness of the cracks a maximum spacing of 5 feet centres for the grout holes is advisable. At this spacing 180 holes would be required to grout the entire required 900 feet length of the proposed curtain. Drilling would total 9,900 feet and vertical holes drilled with an AX size solid bit would be satisfactory.

It is believed that the cracks would be groutable with thin mixtures of cement grout. Tests should be made on the existing drill holes to confirm this opinion.

The only alternative to grouting would be to form a clay blanket over the inlet area for leakage. This would need to be at least 1 foot thick and protected to prevent erosion by wave action. An area 1500 feet long from 200 feet north of the intersection of the projected centre line of the dam with the eastern slope of the ridge to beyond the major curve in the reservoir run to the south would need to be blanketed. This is not considered such a permanent and satisfactory solution of the leakage problem as grouting a curtain from the abutment. Estimation of comparative costs would show which treatment would be the more expensive.


Natural sealing of the ingress points for the leakage by silt will not help materially in reducing leakage during the life of the coal field.

#### CONCLUSION AND RECOMMENDATIONS

The test holes have confirmed the opinion expressed previously that leakage water is traversing the rim of the reservoir through a network of interconnecting cracks which individually have narrow openings. These cracks tighten southwards as the ridge forming the rim becomes wider and higher.

Prevention of leakage by grouting a curtain of holes, at 5 feet centres in the ridge, extending 900 feet south from the left abutment should be possible. A total of 9,900 feet of drilling would effect this curtain. The only alternative would be a protected clay blanket over the 1500 long inlet area of leakage in the reservoir and this would not be so permanent as the grout curtain.

It is recommended that the economy of these two methods of leakage prevention be investigated.

  
W. Johnson  
Senior Geologist  
ANON FERROUS METALS SECTION

DEPARTMENT OF MINES — SOUTH AUSTRALIA  
GEOLOGICAL LOG OF DRILL HOLE

Hole No. AL 1

Project ARONA DAM Location LEFT ABUMENT RIDGE EXTENSION  
R.L. Ground 831.04 Co-ordinates Angle 90° Azimuth  
Purpose of Hole INVESTIGATE LEAKAGE CHANNELS THROUGH RESERVOIR RIM

ROCK TYPE Degree of Weathering Shown in Core	DESCRIPTION	R.L.	Depth and Size of Core	Log	Lift and Core rec'y "	STRUCTURES Joints, Veins, Seams Faults, Crushed Zones	NOTES Water Level (Date) Drilling Water Return Character of Drill Cuttings	PERCOLATION TEST Depth (Ft.) Loss Pres In sure From To GPM PSI length of Test Min.
	Grey angular quartzite boulders	831.04			33			
	Fill				42			
					100			
Limonite staining on joints	Grey fine to medium grained quartzite blackish mangeniferous staining along certain beds	825.04 NX			108			
Quartzite hard to moderately hard			10		100		JOINT COUNT 90	31.8.62
					117			R.L. 820.4
Shaly sandstone beds soft	Grey translucent medium to coarse grained quartzite	813.54						
			20		98		ditto	
					107		ditto	
					108			23.41 85 10 1
					108			1.3 20 1
					108			28 40 1
	Grey fine to coarse grained quartzite interbedded with whitish grey shaly sandstone	800.71	30				JOINT COUNT 120	
	Grey to pinkish grey medium to coarse grained quartzite						Sub-vertical joints	
					93		" " "	
					100		" " "	
		780.04 41						

NOTES

- Overall core recovery = 95.3%
- Individual joints not indicated
- Joint Sets  
DIP  
1. 42°-60° at 130° to bedding dip  
2. 75°-78° " 100 " " "  
3. 35° " 150 " " "  
4. 15° " 270 " " "  
5. 50° " 290 " " "

Drill No.	Logged	Vert. Scale
Type	Sheet No.	Sheet of
Driller	Drawn	Drawing No.
Commenced	Checked	
Completed	Submitted	

250-7.60 8038

Project AR00NA DAM Location LEFT ABUMENT RIDGE EXTENSION  
R.L. Ground 876.55 Co-ordinates — Angle 90 Azimuth —  
Purpose of Hole INVESTIGATE LEAKAGE CHANNELS THROUGH RESERVOIR RIM

*NOTES*

- 1 Overall core recovery = 97%
- 2 Only crushed zones & zones of exceptionally closely spaced joints indicated
- 3 Joints -

COUNT		Set	Dips.	
INTERVAL	NO.			
10'0" to 33'8"	150	1.	42°-60° at 130° to bedding dip	
33'8" to 52'6"	120	2.	75°-78° at 100° " " "	
52'8" to 71'0"	200	3.	35° " 150° " " "	
71'0" to 80'0"	80	4.	15° " 270° " " "	
		5.	50° " 230° " " "	

Drill No. ....	Logged .....	Vert. Scale.....
Type .....	Sheet No. ....	Sheet .. of ...
Driller .....	Drawn .....	
Commenced .....	Checked .....	Drawing No. ....
Completed .....	Submitted .....	250 - 7.60 8036

DEPARTMENT OF MINES — SOUTH AUSTRALIA  
**GEOLOGICAL LOG OF DRILL HOLE**

Hole No. **AL 3**

Project **AROONA DAM** Location **LEFT ABUTMENT RIDGE EXTENSION**  
 R.L. Ground **874.05** Co-ordinates **-** Angle **90** Azimuth **-**  
 Purpose of Hole **INVESTIGATE LEAKAGE CHANNELS THROUGH RESERVOIR RIM**

ROCK TYPE Degree of Weathering Shown in Core	DESCRIPTION	R.L.	Depth and Size of Core	Log	Lift and Core rec'y %	STRUCTURES Joints, Veins, Seams Faults, Crushed Zones	NOTES Water Level (Date) Drilling Water Return Character of Drill Cuttings	PERCOLATION TEST Depth (Ft.) From To Loss Pres in sure GPM PSI lent of Test Min.
		<b>874.05</b>						
	Pinkish buff angular quartzite boulders in brownish & pinkish buff silty & slightly clayey grit (Talus)			Δ Δ	18			
	Grey quartzite in angular fragments			Δ Δ	101			
Quartzite hard to medium hard Gypsum present in cracks to 19' 0"	cemented by pinkish buff coarse grained calclitic grit.			Δ Δ	71	Core broken into pieces 2" to 3" long with much quartzite - rubble		
	Pinkish grey & whitish grey, with some greenish grey bands faintly bedded fine to medium grained quartzite - some coarse layers				95	Joint set 3 Vertical joint & joints sets 1, 4, 9, 5.		
					100	Fractured zone		
					100	Heavily jointed		
					100	Vertical joint Possible fault gouge 13 joints of all sets		
					100	Plentiful joints set 1 tight & cemented		
					100	Core broken in pieces along bedding plane partings & vertical joints		
					100	8 Joints	<b>835.82</b>	
					100	6 Joints sets 1, 2, 9, 4.	<b>31.7.62</b>	
as coating on joint faces	Pinkish grey fine grained to very coarse grained quartzite in beds 1/8" to 2" thick				100	Joints 1" - 2" apart.		4 1/2 80 13 - 5
					86			
					100	49 Joints of all sets.		52 80 63 10' 2 8-7 20' 2
					88			
	Pinkish grey coarse grained quartzite inter bedded with pinkish & greenish grey fine to medium grained quartzite with some shaly laminations				93			
	Blueish grey shaly fine sandstone & pinkish to yellowish fine to medium grained sandstone in 1/8" to 1/4" beds.				104	47 Joints of all sets in this section		
	Yellowish green grey shaly sandstone				98	Possible fault par! to bedding 1" crushed shaly sandstone		
					109			72 80 116 10' 3 168 20 2 1/2 2-2 40 2
	Grey translucent fine to medium grained sandstone with pinkish spots in top 2'				112	30 to 35 joints of all sets. Core broken along vertical joint intersecting joint sets 1, 9, 2.		
		<b>793.55 80</b>						

**NOTES.**

1. Overall core recovery = 88%
2. Very little limonitic staining
3. Jointing not so closely spaced
4. Joint sets.

1 42°-60° at 190° to bedding dip  
 2 75°-78° " 100° " " "  
 3 35° " 150° " " "  
 4 15° " 270° " " "  
 5 50°- at 290° to bedding dip

Drill No.	Logged	Vert. Scale
Type	Sheet No.	Sheet of
Driller	Drawn	Drawing No.
Commenced	Checked	
Completed	Submitted	250-7.60 8036



DEPARTMENT OF MINES — SOUTH AUSTRALIA  
GEOLOGICAL LOG OF DRILL HOLE

Hole No. **AL 4**

Project **AROONA DAM** Location **LEFT ABUTMENT RIDGE EXTENSION**  
R.L. Ground **876.54** Co-ordinates Angle **90** Azimuth  
Purpose of Hole **INVESTIGATE LEAKAGE CHANNELS THROUGH RESERVOIR RIM**

ROCK TYPE Degree of Weathering Shown in Core	DESCRIPTION	R.L.	Depth and Size of Core	Log	Lift and Core rec'y %	STRUCTURES Joints, Veins, Seams Faults, Crushed Zones	NOTES Water Level (Date) Drilling Water Return Character of Drill Cuttings	PERCOLATION TEST Depth (Ft.) Loss Pres In sure From To GPM PSI length of Test Min.
	Brown talus angular hard quartzite boulders in brown slightly clayey silt sized quartz sand	876.54						
Quartzite hard to medium hard predominant reddish tinge to whole core due to deposition of interstitial limonite	Slightly pinkish grey translucent coarse grained moderately hard quartzite with brown subspherical splints formed by interstitial staining					Abundant joints & fractures.		
	Slightly greenish-grey med. hard arg quartzite.					Joints principally of set ① spaced maximum 4" apart, average spacing 1" to 2". All joint cracks partially filled & cemented with yellow powdery material & black manganese hard cement vertical joint Possible fault zone parallel to bedding		
	Neutral to pinkish quartzite with faint bedding laminations predominantly fine grained.							
	Grey fine grained quartzite & pink grey medium to coarse grained spotted quartzite in beds varying from 8" to 3" true thickness.					Strongly jointed core		
						Core broken in pieces		
						Greenish clay seam		
						Core broken along numerous Fractured core joints of sets ① & ②		

NOTES:

- Overall core recovery = 94%.
- Individual joints not indicated.
- Joint sets:

- 42° to 60° at 190° to bedding dip
- 75° to 78° at 100°
- 35° at 150°
- 15° at 270°
- 50° at 290°

Joint counts:


N°





18'6" to 36'0" 180 - 200  
47'10" to 65'6" 140 - 150

Drill No.  
Type  
Driller  
Commenced  
Completed

Logged  
Sheet No.  
Drawn  
Checked  
Submitted

Vert. Scale  
Sheet of  
Drawing No.





Surface profile ———  
 Assumed talus bedrock interface: - - -  
 Assumed groundwater profile: - - -

Vertical scale for cross sections and longitudinal section 1" = 20'  
 Horizontal scale for cross sections 1" = 50'  
 Horizontal scale for longitudinal section 1" = 100'

To accompany report by W. Johnson.

<b>S.A. DEPT. OF MINES</b>				
<b>AROONA DAM GEOLOGICAL INVESTIGATION</b>				
<b>SECTIONS ACROSS &amp; ALONG RIDGE FORMING RESERVOIR RIM</b>				
<b>DOWNSTREAM OF DAM - LEFT ABUTMENT</b>				
Associated Drawing	No.	No.	Amendment	Exd.
<div style="display: flex; justify-content: space-between;"> <div>             Req. No. C.M. Compiled from           </div> <div>             Approved  Director of Mines           </div> <div>             Passed 18/5 Ckd. Exd.           </div> <div>             Scale: as above  <b>62-613</b>              Date 30-8-62           </div> </div>				