

DEPARTMENT OF MINES SOUTH AUSTRALIA

GEOLOGICAL SURVEY
ENGINEERING DIVISION

MOUNT GAMBIER PUMPING STATION
GEOLOGICAL PROGRESS REPORT NO. 2
SEPTEMBER 1965

Ъy

D.H. Stapledon

Supervising Geologist

Page

DEPARTMENT OF MINES SOUTH AUSTRALIA

MOUNT CAMBIER PUMPING STATION GEOLOGICAL PROGRESS REPORT NO. 2 SEPTEMBER 1965

by

D. H. Stapledon Supervising Goologist ENGINEERING DIVISION

CONTENTS

introduction	3
NOTES ON TRENCH EXPOSURES	1
Above Approx. R.L. 275	1
Below Approx. R.L. 275	2
examination of basalt layer	. 2
conclusion	3
REFERENCE 1.	4
Pigures	

Fig. No.	j.	Title	•	Ref. No.
1	Proposed Mt. Skotches s	Cambier Pumping howing Goology	Station.	8 4017 Rd 17

Mt. Cambier Pumping Station Skipway and Rising Main Geological Record During Construction

> Rept. Bk. No. 61/68 G.S. No. 3248 D.M. 1486/62

14th September, 1965

DEPARTMENT OF MINES SOUTH AUSTRALIA

MOUNT GAMBIER PUMPING STATION
GEOLOGICAL PROGRESS REPORT NO. 2
SEPTEMBER 1965

INTRODUCTION

At the request of the Resident Engineer, Southern District, Engineering and Water Supply Department, an inspection was made on the 1st September, 1965, of excavations in progress at the site of the Nount Cambier Pumping Station.

Progress Report No. 1 dated December 1964 (Ref. 1) sets out details of proposed pumping station and pipeline.

Excavation of the pipeline trench above the site (Fig. 1)

is about 60 percent complete. The excavation has been carried out using hand tools.

NOTES ON TRENCH EXPOSURES

of the eastern wall. Above R.L. 275 the material removed has been mainly baseltic ash consisting essentially of poorly graded sands and gravels. The ash mostly shows poorly defined bedding or layering, as shown on Fig. 2, east face elevation. Much of the material is uncemented, loose, and friable. Some horizons however are partly cemented to form materials grading from very strong soils into weak rocks. The wet strengths of these materials are generally not noticeably lower than their dry strengths.

Excavation of the cutting has removed meat of the nearsurface disturbed material, except on the eastern edge where a
mass of partly cemented ash, probably slide material, lies
steeply against horizontally bedded uncemented ash. At the
boundary of the two materials is an old fissure, now sand filled,
which dips steeply downslope. The surface expression of these
features was noted earlier (Ref. 1) as a probable slide scar.

Below Approx. R.L. 275

exposed loosely packed, irregularly shaped blocks of accriscous basalt. A pilot trench 2 ft. wide excavated up to 6 ft. into this material has shown that it can be excavated readily by hand methods. This material was shown in Fig. 1 (Ref. 1) as "possible slumped material", concealing the upper surface of the basalt layer. The material now exposed appears to be a pocket of broken up and contaminated lava, extending several feet below the normal surface of the lava flow. Because of its very loose nature it was planned to cut this material back to a slope of 45° above the basalt layer. From the new exposures it appears likely that cutting this material back to 45° may remove most of it, and just expose the basalt layer.

EXAMINATION OF BASALT LAYER

The construction activity has resulted in cleaning off of vogetation cover from the baselt below and adjacent to the trench, and the structure of the baselt mass can now be more clearly seen.

In the gully immediately to the east of the base of the trench three near-vertical joints are visible. These joints are gaping between 0.2 and 0.5 ft. and are probably partly filled with soil. They appear to strike within 30° of the general direction of the hillside, and occur very approximately at herizontal distances of 5, 15 and 50 ft. in from the face of the pumping station cutting. (Fig. 2, sketch plan).

These cracks in the baselt are immediately above the large collepsed block in the weathered limestone underlying the baselt (Fig. 1). There may be some direct connection between this cracking in the baselt and the collepsed block below, but this need not necessarily be so. As pointed out in Report No. I such opening up of joints adjacent to very steep slopes is a part of the normal mechanical weathering process. In addition some opening up of joints would have occurred initially as the lava solidified and cooled, and again during later explosions. The Access Tunnel showed numerous gaping joints.

CONCLUSION

- 1. Excavation of the pipeline trench has removed near-surface disturbed materials, and the materials exposed in the base of the trench are very little disturbed and appear stable. At the top of the cutting on each side however, it may be necessary to smooth off the sharp ridges formed at the intersection of the cutting with the matural slopes.
- 2. Below R.L. 275 the excavation is incomplete, but it appears likely that most of the material down to the proposed excavation level can be removed by hand methods.


3. The problem of gaping joints in the basalt is considered worthy of further investigation when excavation of the trench has been completed, exposing more of the basalt. Detailed geological sections are desirable before the type of support for the basalt is decided upon. It is clear that if anchor bars or cables are used, these would have to be much longer than the rock bolts originally intended, and that careful caulking and dental treatment of open joints will be required.

D. H. Stapledon
Supervising Geologist
ENGINEERING DIVISION

DHS : AGK 14/9/65

Reference 1

Stapledon, D.H., 1964. "Mount Gambier Pumping Station,
Geological Progress Report No. 1. S.A. Dept. of
Mines, Rept. Bk. No. 59/134.



SKETCH ELEVATION EAST FACE

DIAGRAMMATIC IN PART

