

DEPARTMENT OF MINES AND ENERGY
SOUTH AUSTRALIA

GEOLOGICAL SURVEY

FOUNDATION DRILLING AT
ROBE SLIPWAY - LAKE BUTLER

by

A.F. WILLIAMS
GEOLOGIST

ENGINEERING DIVISION

Rept. Bk. No. 79/21
G.S. No. 6140
D.M. No. 86/63
Eng. No. 1979/NA10

DEPARTMENT OF MINES COUNTY RESERVEMENT

POINT LOCATION

LATITUDE OR EAST	LONGITUDE OR NORTH	ZONE
64	71	79

10 20 30 40 50 60 70 80

2 FOUNDATION DRILLING AT RØBE SLIPWAY - LAKE BUTLER (3 FIGS)

2 1

TITLE

1	10	14	20	30	40	50	60	70	80
3	A. F. WILLIAMS, A. F.								
	ORGAN. OR					AUTHORS			
	COMPANY								

1	3
3	1

COMPANY

10 20 30 40 50 60

AUTHORS

MAP REFERENCES	
10	14
ROBE	LAKE BUTLER
22	26
LAKE BUTLER	OTWAY BASIN
34	39
LICENCE AREA	

ON EVERY

WATERHOUSE

40	43	47	51	55

HUNDRED SECTIONS HUNDRED SECTIONS

CARD

1 3
6 1

ENGINEERING GEOLOGY
MAJOR KEYWORD
DRILLING
LAKE

FOUNDATION
GEOLOGICAL LOG

DIAMOND ~~DRILL~~
DRILLING
GAMBER LOG

BRIDGEWATER
FORMATION
CANADIAN

DATE _____

CHECKED

DATE _____

6.3.7.9

<u>CONTENTS</u>	<u>PAGE</u>
ABSTRACT	1
INTRODUCTION	1
GEOLOGY	1
ROCK PROPERTIES	2
CAVITIES	2
DISCUSSION	3

APPENDIX 1. Drill Hole Logs

FIGURES		
<u>Number</u>	<u>Title</u>	<u>Dwg. No.</u>
1	Locality Plan	S13873
2	Drill hole locations	S13874
3	Geological section along slipway	79-101

DEPARTMENT OF MINES AND ENERGY
SOUTH AUSTRALIA

Rept.Bk.No. 79/21
G.S. No. 6140
D.M. No. 86/63
Eng. No. 1979/NA10

FOUNDATION DRILLING AT
ROBE SLIPWAY - LAKE BUTLER

ABSTRACT

Foundation testing for strengthening the existing slipway at Lake Butler, Robe has shown the presence of medium strong rock (Bridgewater Formation limestones) at a depth of less than 2 m which should provide an adequate bearing horizon for the structure. However a significant number of solution cavities, probably in the form of narrow vertical pipes, were intersected which could cause localised weakening of the rock mass. It is suggested that steel foundation piles be used and each pile be driven to refusal.

INTRODUCTION

A request was received from the South Australian Department of Marine and Harbours in October, 1978 to provide geologic detail below the existing slipway at Lake Butler, Robe (see Fig. 1). A new slipway is to be constructed on piles to bedrock. Three diamond drill holes were completed during the 9th to the 13th January. The rig was mounted on a boat cradle run down the slipway. Unfortunately silt and sand up to 1.5 m deep prevented drilling right at the end of the slipway. A diver was able to jet sediment away at about 8 m from the end.

Three holes were drilled to depths of 10.0, 12.2 and 13.4 m respectively 54, 30 and 70 m from the zero chainage point on the slipway (see Fig. 2).

GEOLOGY

All holes intersected Bridgewater Formation limestones at or near surface to about 9 m. MC59 and 60 struck Gambier Limestone at 11.4 and 9.0 m while MC59 was not drilled deep

enough to intersect Gambier Limestone, but the contact is expected only 1-2 m below the hole bottom. A geologic section down the slipway is shown on Fig. 3. Logs of all holes appear in Appendix I and a summary of rock properties is given in Table I.

TABLE I
ROCK PROPERTIES

<u>Formation and lithology</u>	<u>Strength</u>	<u>Condition</u>	<u>Structure (including solution features)</u>
Bridgewater Formation, granular limestone (one thin clay band (0.25 m) in MC59)	Medium strong, weaker near top	Slightly weathered at top 1 metre (calcreted)	No fractures, core parts generally along bedding planes in pieces 1 to 30 cm when drilled. Solution features common, ranging in size from 1 to 5 cm. Some show lining by secondary carbonate. Major cavities in all three holes - see below.
Gambier Limestone, fossiliferous limestone	Weak to medium strong	Some recrystallization near top gives better cemented rock	No fractures, no obvious bedding. Core parts irregularly in 5 to 25 cm pieces when drilled. Core broken into chips where soft.

CAVITIES


No water returns were obtained in all three holes within the Bridgewater Formation and the driller reported silt in these sections. It is suspected that there are moderate size vertical solution pipes, varying from 0.3 to 1 m in diameter as often seen in road cuttings, occurring through this formation. From the logs they appear restricted to the Bridgewater Formation but it is felt that insufficient thickness of Gambier Limestone has been penetrated to preclude their presence in that formation. They do not appear within the drill holes 9.5 m below the slipway surface.

DISCUSSION

Drilling has shown that bedrock of sufficient strength to form a bearing horizon occurs at shallow depth (maximum 2 m) beneath the existing slipway.

Lack of core recovery and drilling water returns on all holes drilled indicate the presence of narrow fissures formed by solution effects within the limestone. These fissures may extend to considerable depth and form the main geological hazard on the site. In view of this it is recommended that steel piles be used, designed to effect maximum penetration into the limestone, and that each pile be driven to refusal.

AFW:ZV


A.F. WILLIAMS

APPENDIX 1

DRILL HOLE LOGS

PROJECT: ROBE SLIPWAY

DEPARTMENT OF MINES SOUTH AUSTRALIA
ENGINEERING DIVISION

HOLE NO. M59

LOCATION OR CO-ORDS: SLIPWAY LAKE
BUTLER, ROBE

LOG OF DIAMOND DRILL HOLE

UNIT/STATE NO

SEC. HD.

EL Surface

EL ref. point

Datum

SERIAL NO.

FOLDER NO.

GEOLOGICAL DESCRIPTION OF CORE	② GROUP SYMBOL	① STRENGTH TERM	HOLE Dia. mm	DEPTH m	GRAPHIC LOG	③ R.Q.D.%	STRUCTURES JOINTS, VEINS, SEAMS, SHEARED ZONES, CRUSHED ZONES	LIFT CORE LOSS% 10 5 50	WATER LEVEL DATE	CASING DRILL WATER LOSS% 0 100	④ WATER PRESSURE TESTS LUCEONS 0.5 1 5 10 50
No rec - driller reports silt CALCRETE - weathered limestone silt, cemented sand size grains LIMESTONE, cemented carbonate grains or shell fragments 0.1 to 1mm, calcareous cement, some pockets (20-30mm) of calcrete as above. Traces of horizontal bedding. BRIDGEWATER FORMATION.						75 50 25	Breaks irregularly on drilling No fractures apparent. Minor solution features to 10mm				
No recovery - driller reports silt and sand							Cavity probably infilled to some extent				
LIMESTONE as above 0.2 to 1.8m Both horizontal and cross bedding noticeable. Speckled gray, cream + yellow brown as above							No fractures apparent - solution features abundant - up to 5-10 cm 6-6.2m with secondary carbonate filling cavities. There on has etched appear ance with most cavities + 2 cm occasional to 3, 4cm.				
No recovery, driller reports silt and sand.							Solution features enlarged to many cm and much more abundant than above.				
LIMESTONE, as above BRIDGEWATER FORMATION							Cavity - probably infilled to some extent				
							As for 6.75-8m T.D. 10.0m				

① ROCK SUBSTANCE

STRENGTH TERM
VS-Very Strong
S-Strong
MS-Medium Strong
W-Weak
VW-Very Weak
SO-Soil properties

CONDITION TERM

 Fresh
Weathered
Altered
Soil properties

Numbers give diametral point load strength (Is) in MPa.

③ ROCK QUALITY DESIGNATION

0-25% Very poor
25-50% Poor
50-75% Fair
75-100% Good to excellent④ (350) Maximum effective pressure
(kilopascals) reached during test.② Substances with soil properties remoulded and
classified by Unified System

DRILL TYPE Mindrill

LOGGED BY: H/W

CIRCULATION: Water

DATE: 17/1/79

HOLE ANGLE: Vertical

BEARING: -

START: 10/1/79

TRACED BY:

FINISH: 10/1/79

DATE:

SHEET.....1 OF 1.....

HOLE NO.	MC 55
----------	-------

LOCATION OR CO-ORDS: *SUPWAY, LAKE BUTLER, ROBE*

LOG OF DIAMOND DRILL HOLE

UNIT/STATE NO

SERIAL NO

FOLDER NO.

SEC.	HD.	EL Surface	EL ref. point	Datum
------	-----	------------	---------------	-------

GEOLOGICAL DESCRIPTION OF CORE	(2) GROUP SYMBOL	(1) STRENGTH TERM	HOLE Dia.	DEPTH m	GRAPHIC LOG	R.Q.D.% 75 50 25	STRUCTURES JOINTS, VEINS, SEAMS, SHEARED ZONES, CRUSHED ZONES	LIFT CORE LOSS% 10 5.50	WATER LEVEL DATE	CASING DRILL WATER LOSS % 0 100	WATER PRESSURE TESTS LUGEONS 0.5 1 5 10 50
No recovery - driller reports silt											
<u>LIMESTONE</u> , cemented carbonate grains and fragments 0.1 to 2mm Calcareous cement - partly weathered (calcreted) 0.75 to 1.30m Traces of horiz. bedding. Speckled grey, yellow brown. Minor calcrete No recovery - driller reports silt				1	Core in pieces 2-25cm Breaks irregular during drilling		No fractures apparent, odd solution feature about 0.95m - several cm in size and lined with secondary carbonate				
				2			Cavity, probably infilled to some extent				
				3							
				4							
<u>LIMESTONE</u> as above, few chips of concrete calcrete at 4.50-4.60m - also shells at 5.0m - probably from above Horizontal and cross bedding obvious.				5	Core in pieces mainly 10-30cm Breaks along bedding plane during drilling		No fractures apparent - solution features more prevalent and abundant from 8.40m 1-5cm in size				
<u>BRIDGE WATER FORMATION</u> As ABOVE.				6							
				7							
				8							
				9							
				10	Core in pieces 1-7cm						

① ROCK SUBSTANCE

STRENGTH TERM

VS-Very Strong
S-Strong
MS-Medium Strong
W-Weak
VW-Very Weak
SO-Soil properties

CONDITION TERM



Numbers give diametral point load strength (Is) in MPa.

③ ROCK QUALITY DESIGNATION

0-25% Very poor
25-50% Poor
50-75% Fair
75-100% Good to excellent

④ (350) Maximum effective pressure (kilopascals) reached during test.

DRILL TYPE *Mindrill*

LOGGED BY: AFW

CIRCULATION: *Water*

DATE: 17/1/79

HOLE ANGLE: *Vertical*

BEARING: —

START: 11/1/79

TRACED BY:

FINISH: 11/1/79

DATE:

② Substances with soil properties remoulded and classified by Unified System

SHEET 1 OF 2

PROJECT: ROBE SLIPWAY

DEPARTMENT OF MINES SOUTH AUSTRALIA
ENGINEERING DIVISION

HOLE NO. MC 59

LOCATION OR CO-ORDS:

LOG OF DIAMOND DRILL HOLE

UNIT/STATE NO

SEC.

HD.

EL Surface

EL ref. point

Datum

SERIAL NO.

FOLDER NO.

GEOLOGICAL DESCRIPTION OF CORE

②
GROUP
SYMBOL①
STRENGTH
TERM

HOLE DIA.

DEPTH IN
GRAPHIC
LOG③
R.Q.D.%STRUCTURES
JOINTS, VEINS, SEAMS,
SHEARED ZONES, CRUSHED ZONESLIFT
CORE
LOSS%WATER
LEVELCASING
LEVELDRILL
WATER
LOSS%WATER
PRESSURE
TESTS
LUGEONS

④

10

5.50

DATE

0 100

0.5

5 10

50

LIMESTONE as above, becomes
yellow to cream after 10.20mNOTE 0-11.1 BRIDGEWATER
FORMATIONCLAY, sandy fgt, grains to 2mm, brown
grey to khaki, stiffLIMESTONE as above till 11.40m
then comprised of shell and bryo
zoal fragments 3-15mm+.
Calcareous cement. No obvious
bedding. Coarser grained than
above.

SEQUENCE

0-11.1 BRIDGEWATER
FORMATION11.1-11.35 ? CLAY INFILLED
CAVITY11.35-11.40 BRIDGEWATER
FORMATION11.40-12.20 GAMBIER
LIMESTONECore in
pieces
2-10cmSolution features as for B 40m
to 10 cm till 10.40m when
less prevalent.Core in
pieces
5-15cm

No fractures.

Core in
pieces
mainly
15-20cmNo fractures. Solution features
to several cmBreaks
irregular
upon
drilling

T.D. 12.2m

Below lake bed

Nil

Not tested

① ROCK SUBSTANCE

STRENGTH TERM
VS-Very Strong
S-Strong
MS-Medium Strong
W-Weak
VW-Very Weak
SO-Soil properties

CONDITION TERM

 Fresh
Weathered
Altered
Soil properties

Numbers give diametral point load strength (Is) in MPa.

② Substances with soil properties remoulded and
classified by Unified System

③ ROCK QUALITY DESIGNATION

0-25% Very poor
25-50% Poor
50-75% Fair
75-100% Good to excellent④ (350) Maximum effective pressure
(kilopascals) reached during test.

DRILL TYPE

LOGGED BY: AFW

CIRCULATION:

DATE: 17/1/79

HOLE ANGLE:

BEARING:

START:

TRACED BY:

FINISH:

DATE:

SHEET....2 OF 2....

PROJECT: ROSE SLIPWAY

DEPARTMENT OF MINES SOUTH AUSTRALIA
ENGINEERING DIVISION

LOCATION OR CO-ORDS: SLIPWAY LAKE
BUTLER ROBE
SEC. HD.

LOG OF DIAMOND DRILL HOLE

HOLE NO. 156

UNIT/STATE NO.

SERIAL NO.

FOLDER NO.

EL Surface

EL ref. point

Datum

GEOLOGICAL DESCRIPTION OF CORE

②
GROUP
SYMBOL

①
STRENGTH
TERM

HOLE Dia.

DEPTH m

GRAPHIC
LOG

③
R.Q.D.%

STRUCTURES
JOINTS, VEINS, SEAMS,
SHEARED ZONES, CRUSHED ZONES

LIFT
CORE
LOSS%

WATER
LEVEL

CASING
DATE

DRILL
WATER
LOSS%

WATER
PRESSURE
TESTS
LUGEONS

④

No recovery - driller reports
silt

LIMESTONE cemented carbonate
grains and shell fragments 0.1 to 2mm
calcareous cement. No obvious bedding.
No recovery, driller reports silt.

Core in
pieces 1-
2-8 cm

No fractures apparent. Minor solution
features 1-2cm. Core breaks
irregularly.
Cavity. probably infilled to some
extent.

LIMESTONE as above. Horizontal
and cross bedding present. Speckled
grey & cream as above.

Core in
pieces 1-
8 cm
Fractures along
bedding
planes

No fractures present. Minor solution
features 1-2cm.

LIMESTONE as above, bedding not ob-
vious.

0-9m BRIDGEWATER FORMATION

LIMESTONE comprised mainly of
bryozoan fragments, 5-10mm. Shelly
cemented by carbonate - softer
than above. No obvious bedding

Core in
fragments
large
chipping
pieces
8-35 cm
Grains
irregular
14 cm

No fractures present, core very
broken - suggestive of abundant
solution features - some chippings
may be infilling from cavity above.
No fractures evident. Some solution
features 1-2cm.

Below table level

Nil

Not tested

① ROCK-SUBSTANCE

STRENGTH TERM
VS-Very Strong
S-Strong
MS-Medium Strong
W-Weak
VW-Very Weak
SO-Soil properties

CONDITION TERM

Fresh
Weathered
Altered
Soil properties

Numbers give diametral point load strength (Is) in MPa.

② Substances with soil properties remoulded and
classified by Unified System

③ ROCK QUALITY DESIGNATION

0-25% Very poor
25-50% Poor
50-75% Fair
75-100% Good to excellent

④ (350) Maximum effective pressure
(kilopascals) reached during test.

DRILL TYPE Mindrill

LOGGED BY: AFW

CIRCULATION: Water

DATE: 18/1/79

HOLE ANGLE: Vertical

BEARING: —

START: 13/1/79

TRACED BY:

FINISH: 13/1/79

DATE:

SHEET.....1 OF 2...

PROJECT: ROBE SLIPWAY

DEPARTMENT OF MINES SOUTH AUSTRALIA
ENGINEERING DIVISION

HOLE NO. MC60

LOCATION OR CO-ORDS:

LOG OF DIAMOND DRILL HOLE

UNIT/STATE NO.

SEC.

HD.

EL Surface

EL ref. point

Datum

SERIAL NO.

FOLDER NO.

GEOLOGICAL DESCRIPTION OF CORE

②
GROUP
SYMBOL

①
STRENGTH
TERM

VS
MS
S
W
VW
SO

DEPTH m

GRAPHIC
LOG

③
R.Q.D.%
75 50 25

STRUCTURES
JOINTS, VEINS, SEAMS,
SHEARED ZONES, CRUSHED ZONES

LIFT
CORE
LOSS%

WATER
LEVEL

CASING
LOSS%

DRILL
WATER
LOSS%

WATER
PRESSURE
TESTS
LUGEONS

④

DATE

0.5 1 5 10 50

LIMESTONE as above - softer.

0 - 13.4m GAMBIE LIMESTONE

No fractures - solution features
as above

drilling
core took
10.3, 11.3
11.5m

T.D. 13.4m

Below lake bed

11.1

Not tested

① ROCK SUBSTANCE

STRENGTH TERM

VS-Very Strong

S-Strong

MS-Medium Strong

W-Weak

VW-Very Weak

SO-Soil properties

CONDITION TERM

Fresh

Weathered

Altered

Soil properties

Numbers give diametral point load strength (Is) in MPa.

② Substances with soil properties remoulded and
classified by Unified System

③ ROCK QUALITY DESIGNATION

0-25% Very poor

25-50% Poor

50-75% Fair

75-100% Good to excellent

④ (350) Maximum effective pressure
(kilopascals) reached during test.

DRILL TYPE

LOGGED BY: AFW

CIRCULATION:

DATE: 18/1/79

HOLE ANGLE:

BEARING:

START:

TRACED BY:

FINISH:

DATE:

SHEET...2... OF...2...

JOB No. 1185





FIG. 1

DEPARTMENT OF MINES AND ENERGY SOUTH AUSTRALIA		SCALE: As shown
COMPILED: A.F.W.		DATE: 1/2/79
DRN P.D.	CKD	PLAN NUMBER
W.D.R.		513873
ROBE SLIPWAY - LAKE BUTLER		
LOCALITY PLAN		



Traced from S.A.H.B plan 17469 28/10/63
68

Site positions from R.Dunn S.A.H.B., Beachport.

FIG. 2

		DEPARTMENT OF MINES AND ENERGY SOUTH AUSTRALIA	SCALE: As shown
COMPILED A.F.W.		ROBE SLIPWAY - LAKE BUTLER DRILL HOLE LOCATIONS (Approximate)	DATE: 1/2/79
DRN: P.D.	CKD		PLAN NUMBER
W.D.R.			S13874





FIG. 3

DEPARTMENT OF MINES AND ENERGY SOUTH AUSTRALIA		SCALE As shown.
COMPILED A.F.W.	ROBE SLIPWAY - LAKE BUTLER GEOLOGICAL PLAN	DATE 5/1/79
DRN P.D. CKD		PLAN NUMBER
W.D.P.		79-101